REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	5/10/2012	**Time:**	8:54 AM
Name of School Corporation:	FRANKLIN COMM. SCHOOL CORP.			**Corp ID:**	414225
Address of School Corporation:	750 E SR 44				
City:	Franklin	**Zip:**	46131	**County Number:**	41
VIN:	4DRBUAAN89B681471	**License Number:**	32199	**Bus Number:**	111
Make of Body:	IC Corporation **Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:**	2009
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	A	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.