

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 5/11/2012	Time: 9:29 AM
Name of School Corporation: EDINBURGH COMM. SCHOOL CORP.	Corp ID: 414215	
Address of School Corporation: 202 S Keeley St		
City: Edinburg	Zip: 46124	County Number: 41
VIN: 1BABKC0A94F216066	License Number: 6952	Bus Number: 2
Make of Body: Blue Bird Corporation	Year: 2004	Make of Chassis: Blue Bird Corporation
Bus Type: D	Mileage: Unknown	Year: 2004
Inspection Status: O	Inspected By: John Pang	PE: 6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function
30-1-8	If required, positive door opening device is missing or fails to operate properly.
42-1-2	Floor covering is missing, cut, loose, buckled or bulging.
66-1-3	Any required padding is missing
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.