## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	5/11/2012	Time:	9:14 AM
Name of School Address of Scho	•		BURGH COM 202 S Keeley	IM. SCHOOL CC / St	DRP.	Corp ID:	414215
City:	Edinburg	7	Zip:	46124		County Number:	41
VIN:	1BABKCPA82F203	3098		License Number:	74620	Bus Number:	3
Make of Body:	Blue Bird Corporation	Year: 2	2002	Make of Chassis:	Blue Bird Corporation	Year:	2002
Bus Type:	D			Mileage:	Unknown		
Inspection Status:	0		Inspected Bv:	John Pang		PE:	6196

## Violations - Rejected

Inspection Code	<u>Description</u>
34-1-1	There is significant engine oil or fluid leak from the engine.
66-1-3	Any required padding is missing

## **Violations - Out of Service**

<u>inspection</u> <u>Code</u>	<u>Description</u>
36-2-1	Exhaust leak occurs in the exhaust system prior to the muffler outlet.
99-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
14-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.