REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/15/2012	**Time:**	1:48 PM
Name of School Corporation:	NORTHWEST ALLEN COUNTY SCHOOLS			**Corp ID:**	20225
Address of School Corporation:					
City:		**Zip:**		**County Number:**	2
VIN:	1BABKCPA09F260485	**License Number:**	32112	**Bus Number:**	8
Make of Body:	Blue Bird Corporation **Year:** 2009	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2009
Bus Type:	D	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Tom Merkling	**PE:**	5390

Violations - Rejected

Inspection Code	Description
8-1-1	Required back-up lights do not function.
83-1-5	Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.