REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/22/2012 Time:9:11 AM

Name of School Corporation: BLOOMFIELD SCHOOL DISTRICT

Corp ID: 282920

Address of School Corporation: PO Box 266

City:BloomfieldZip:47424County Number:28VIN:1GBJG31U851187786License Number:65625Bus Number:3corpMake of Body:Mid Bus, Inc. Year:2006Make of Chassis:Carpenter Year:2006

Bus Type: Mileage: Unknown

Inspection Status: R Inspected By: Mark Raper PE: 6473

Violations - Rejected

Inspection Code Description

99-1-10 If the emergency window instructions are illegible or missing. Must be within 6 inches

of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description