REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:5/22/2012 Time:8:36 AMName of School Corporation:BLOOMFIELD SCHOOL DISTRICTCorp ID:282920

Address of School Corporation: PO Box 266

City:BloomfieldZip:47424County Number:28VIN:1HVBBABPXXH208430License Number:B186EBus Number:5Make of Body:AmTranYear:1999

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Mark Raper PE: 6473

Violations - Rejected

| Inspection Code | <u>Description</u> |
|--------------------|---|
| 36-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 34-1-1 | There is significant engine oil or fluid leak from the engine. |
| 11-1-1 | Any body clamp is loose. |
| 91-1-3 | Any rear tire has less than 2/32 inch tread depth |
| 38-1-1 | Mirror or mirror backs that are loose or improperly mounted. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.