REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	5/24/2012	Time:	10:43 AM
Name of School Address of Scho	•		LB CO. CTL. 3326 CR 427	UNTD. SCH DIS	ST	Corp ID:	171835
City:	Waterloo		Zip:	46793		County Number:	17
VIN:	1BAKFCPA5DF289	9820		License Number:	7107	Bus Number:	20
Make of Body:	Blue Bird Corporation	Year:	2013	Make of Chassis:	Blue Bird Corporation	Year:	2013
Bus Type:	С			Mileage:	Unknown		
Inspection Status:	R		Inspected By:	Tom Merkling		PE:	5390

Violations - Rejected

Inspection Code	<u>Description</u>
58-1-1	Any required instrument or gauge is missing.
8-1-1	Required back-up lights do not function.
34-1-1	There is significant engine oil or fluid leak from the engine.
99-1-7	Any emergency window is too difficult to open
81-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure).
63-1-1	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.