

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/24/2012	<b>Time:</b> 8:55 AM
<b>Name of School Corporation:</b> DEKALB CO. CTL. UNTD. SCH DIST	<b>Corp ID:</b> 171835	
<b>Address of School Corporation:</b> 3326 CR 427		
<b>City:</b> Waterloo	<b>Zip:</b> 46793	<b>County Number:</b> 17
<b>VIN:</b> 1BAKGCBA8DF292876	<b>License Number:</b> 9378	<b>Bus Number:</b> 21
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2013	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Bus Type:</b> C	<b>Mileage:</b> Unknown	<b>Year:</b> 2013
<b>Inspection Status:</b> O	<b>Inspected By:</b> Tom Merkling	<b>PE:</b> 5390

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-2	Any seat back or bottom is loose.
74-1-2	The belt cutter is not secured
10-1-3	Any battery is loose in its mounting.
62-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative.
76-1-2	Any shock absorber is leaking fluid
76-1-1	There are any loose, broken, or missing mountings
81-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure).

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.
14-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.