## REPORT OF SCHOOL BUS INSPECTION

Type of 9:10 Annual Date: 5/29/2012 **Time**: Inspection: AM Name of School Corporation: SHELBYVILLE CENTRAL SCHOOLS 737365 Corp ID: **Address of School Corporation:** 803 St Joseph St County City: Shelbyville Zip: 46176 73 Number: License VIN: 4UZAAXBW52CJ64885 B788D **Bus Number:** 20 Number: Make of Blue Bird Year: 2002 Make of Body: Freightliner Year: 2002 Corporation Chassis: Bus Type: С Mileage: Unknown Inspected PE: **Inspection Status:** O John Pang 6196 By:

## Violations - Rejected

# Inspection Code Description

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

#### **Violations - Out of Service**

### Inspection Code Description

36-2-1 Exhaust leak occurs in the exhaust system prior to the muffler outlet.

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.