

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/31/2012	Time:	1:21 PM
Name of School Corporation:	SCHOOL CITY OF HOBART SERVICE CTR	Corp ID:	454730		
Address of School Corporation:	200 S Hobart Rd				
City:	Hobart	Zip:	46342	County Number:	45
VIN:	4DRBUAAN88B557909	License Number:	31558	Bus Number:	7
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Year:	2008	Year:	2008		
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.