REPORT OF SCHOOL BUS INSPECTION

Type of 10:45 Time: Annual Date: 5/31/2012 Inspection: AM Name of School Corporation: **BAUGO COMMUNITY SCHOOLS** 202260 Corp ID: **Address of School Corporation:** 29125 CR 22 W County City: **Elkhart** Zip: 46517 20 Number: License VIN: 1HVBBABP1WH562853 1516 **Bus Number:** Number: Make of IC Thomas Built Buses, Make of Body: **Year:** 1998 Year: 1998 Corporation Inc. Chassis: Bus Type: С Mileage: Unknown Inspection Inspected 0 PE: 8022 Travis Harrold Status: By:

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection

Code

Description

Pront tire has less than 4/32 of an inch tread depth when measured in two (2) adjacent

91-2-5 Front tire has less than 4/32 of an inch tread depth when measured in two (2) adjacent major grooves at three (3) locations spaced equally around the outside of the tire

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.