

## REPORT OF SCHOOL BUS INSPECTION

|                                                              |                                   |                                               |
|--------------------------------------------------------------|-----------------------------------|-----------------------------------------------|
| <b>Type of Inspection:</b> Annual                            | <b>Date:</b> 6/5/2012             | <b>Time:</b> 9:33 AM                          |
| <b>Name of School Corporation:</b> NORTHWESTERN SCHOOL CORP. |                                   | <b>Corp ID:</b> 343470                        |
| <b>Address of School Corporation:</b> 3075 N Washington St   |                                   |                                               |
| <b>City:</b> Kokomo                                          | <b>Zip:</b> 46901                 | <b>County Number:</b> 34                      |
| <b>VIN:</b> 1BAKF CPA38F253355                               | <b>License Number:</b> 31556      | <b>Bus Number:</b> 27                         |
| <b>Make of Body:</b> Blue Bird Corporation                   | <b>Year:</b> 2008                 | <b>Make of Chassis:</b> Blue Bird Corporation |
| <b>Year:</b> 2008                                            |                                   | <b>Year:</b> 2008                             |
| <b>Bus Type:</b> C                                           | <b>Mileage:</b> Unknown           |                                               |
| <b>Inspection Status:</b> R                                  | <b>Inspected By:</b> Randy McPike | <b>PE:</b> 7018                               |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                 |
|------------------------|------------------------------------------------------------------------------------|
| 30-1-8                 | If required, positive door opening device is missing or fails to operate properly. |
| 74-1-2                 | The belt cutter is not secured                                                     |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.