

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Registration	<b>Date:</b>	6/5/2012	<b>Time:</b>	1:36 PM
<b>Name of School Corporation:</b>	RSI TRUCK & BUS REPAIR, INC	<b>Corp ID:</b>	45005Z		
<b>Address of School Corporation:</b>	3333 Sheffield Ave				
<b>City:</b>	Hammond	<b>Zip:</b>	46327	<b>County Number:</b>	45
<b>VIN:</b>	1HVBBABL71H504848	<b>License Number:</b>	B669g	<b>Bus Number:</b>	6
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2001	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
93-1-4	Any front turn signal does not function properly
8-1-1	Required back-up lights do not function.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
93-2-1	Any rear turn signal does not function properly
85-2-1	Any stop arm light is inoperative
90-2-1	Two (2) or more taillights or brake lights do not function
34-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire.

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**