REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/7/2012	**Time:**	10:17 AM
Name of School Corporation:	MT. VERNON COMM. SCHOOL CORP.			**Corp ID:**	303135
Address of School Corporation:	1776 W SR 234				
City:	Fortville	**Zip:**	46040	**County Number:**	30
VIN:	1BABNCPH4AF275001	**License Number:**	74261	**Bus Number:**	20
Make of Body:	Blue Bird Corporation **Year:** 2010	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2010
Bus Type:	D	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
30-1-8	If required, positive door opening device is missing or fails to operate properly.
34-1-4	There is a significant fluid leak from the transmission.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.