REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	6/18/2012	**Time:**	10:42 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	1HVBBAAP6VH487793	**License Number:**	15363	**Bus Number:**	5
Make of Body:	Carpenter **Year:** 1997	**Make of Chassis:**	IC Corporation	**Year:**	1997
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Brian Bills	**PE:**	5506

Violations - Rejected

Inspection Code	Description
66-1-3	Any required padding is missing

Violations - Out of Service

Inspection Code	Description
83-2-1	Any part of the step-well or support structure is rusted through

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.