# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 6/22/2012 | **Time:** | 2:54 PM |
| **Name of School Corporation:** | CANNELTON CITY SCHOOLS | | | **Corp ID:** | 626340 |
| **Address of School Corporation:** | 109 S 3rd St | | | | |
| **City:** | Cannelton | **Zip:** | 47520 | **County Number:** | 62 |
| **VIN:** | 2GBHG31K4M4123099 | **License Number:** | 71409 | **Bus Number:** | 2 |
| **Make of Body:** | Chevrolet **Year:** 1991 | **Make of Chassis:** | Wayne | **Year:** | 1991 |
| **Bus Type:** | | **Mileage:** | Unknown | | |
| **Inspection Status:** | R | **Inspected By:** | Kelly Hammond | **PE:** | 6682 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 36-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**