REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/22/2012	**Time:**	2:54 PM
Name of School Corporation:	CANNELTON CITY SCHOOLS			**Corp ID:**	626340
Address of School Corporation:	109 S 3rd St				
City:	Cannelton	**Zip:**	47520	**County Number:**	62
VIN:	2GBHG31K4M4123099	**License Number:**	71409	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1991	**Make of Chassis:**	Wayne	**Year:**	1991
Bus Type:		**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description