

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/18/2012 Time: 1:54 PM
Name of School Corporation: INTERLOCAL CAP HEAD START Corp ID: 33002Z
Address of School Corporation: PO Box 449
City: New Castle Zip: 47362 County Number: 33
VIN: 2GBHG31K9P4109445 License Number: 12966 Bus Number: 1
Make of Body: Mid Bus, Inc. Year: 1993 Make of Chassis: Chevrolet Year: 1993
Bus Type: A1 Mileage: Unknown
Inspection Status: O Inspected By: Dave Whitinger PE: 6480

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
68-2-2	There is a severe leakage from any point.

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.