REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	6/28/2012	**Time:**	12:23 PM
Name of School Corporation:		CRAWFORD CO. COMM. SCHOOL CORP				**Corp ID:**	131300
Address of School Corporation:		5808 E Administration Rd					
City:	Marengo	**Zip:**	47140			**County Number:**	13
VIN:	1HVBBABP5XH208769			**License Number:**	B518D	**Bus Number:**	26
Make of Body:	IC Corporation	**Year:**	1999	**Make of Chassis:**	IC Corporation	**Year:**	1999
Bus Type:	C			**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Kelly Hammond			**PE:**	6682

Violations - Rejected

Inspection Code	Description
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.