

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/28/2012 Time: 12:12 PM  
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300  
Address of School Corporation: 5808 E Administration Rd  
City: Marengo Zip: 47140 County Number: 13  
VIN: 1GBL7T1C9XJ106717 License Number: B287f Bus Number: 31  
Make of Body: Chevrolet Year: 2000 Make of Chassis: Chevrolet Year: 2000  
Bus Type: C Mileage: Unknown  
Inspection Status: R Inspected By: Kelly Hammond PE: 6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.