

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/28/2012	<b>Time:</b> 12:01 PM
<b>Name of School Corporation:</b>	CRAWFORD CO. COMM. SCHOOL CORP	<b>Corp ID:</b> 131300
<b>Address of School Corporation:</b>	5808 E Administration Rd	
<b>City:</b> Marengo	<b>Zip:</b> 47140	<b>County Number:</b> 13
<b>VIN:</b> 1GBJG31K391164372	<b>License Number:</b> 81640	<b>Bus Number:</b> 86
<b>Make of Body:</b> Collins Bus Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2009	<b>Mileage:</b> Unknown	<b>Year:</b> 2009
<b>Bus Type:</b>		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Kelly Hammond	<b>PE:</b> 6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------