

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 6/27/2012	<b>Time:</b> 8:31 AM
<b>Name of School Corporation:</b> DUNELAND SCHOOL CORPORATION	<b>Corp ID:</b> 646470	
<b>Address of School Corporation:</b> 601 W MORGAN AVE		
<b>City:</b> Chesterton	<b>Zip:</b> 46304	<b>County Number:</b> 64
<b>VIN:</b> 4DRBUAAN57B378869	<b>License Number:</b> 30024	<b>Bus Number:</b> 2
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2007	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2007	<b>Mileage:</b> Unknown	<b>Year:</b> 2007
<b>Bus Type:</b> C		
<b>Inspection Status:</b> R	<b>Inspected By:</b> David Eggers	<b>PE:</b> 5191

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
21-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative.
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.
66-1-2	Any seat back or bottom is loose.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**