## REPORT OF SCHOOL BUS INSPECTION

Type of 11:08 Re-Inspection Date: 7/12/2012 **Time**: Inspection: AM Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP 131300 Corp ID: **Address of School Corporation:** 5808 E Administration Rd County City: Marengo Zip: 47140 13 Number: License VIN: 1GBJG31K391164372 81640 **Bus Number:** 86 Number: Collins Bus Make of Year: 2009 Chevrolet Year: Make of Body: 2009 Corporation Chassis:

Bus Type: Mileage: Unknown

Inspection Status: A Inspected By: Kelly Hammond PE: 6682

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**