## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 7/12/2012 Time: 1:23 PM

Name of School Corporation: EASTBROOK COMM. SCHOOL CORP. Corp ID: 272815

**Address of School Corporation:** 560 S 900 E

City: Marion Zip: 46952 **County Number: 27** VIN: 1GDHG31F411229808 **Bus Number:** License Number: 715797 Make of Chassis: Mid Bus. Inc. Year: 2002 Make of Body: Mid Bus, Inc. Year: 2002

**Bus Type:** A1 Mileage: Unknown

PE: 7018 **Inspection Status:** R Inspected By: Randy McPike

## **Violations - Rejected**

## Description **Inspection Code**

41-1-2 The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

30-1-8 If required, positive door opening device is missing or fails to operate properly.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.