REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	7/12/2012	**Time:**	1:15 PM
Name of School Corporation:	EASTBROOK COMM. SCHOOL CORP.			**Corp ID:**	272815
Address of School Corporation:	560 S 900 E				
City:	Marion	**Zip:**	46952	**County Number:**	27
VIN:	1GDHG31F811229570	**License Number:**	715796	**Bus Number:**	1
Make of Body:	Mid Bus, Inc. **Year:** 2002	**Make of Chassis:**	Mid Bus, Inc.	**Year:**	2002
Bus Type:	A1	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.
30-1-8	If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**