

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	7/30/2012	Time:	9:27 AM		
Name of School Corporation:	SHERIDAN COMMUNITY SCHOOLS			Corp ID:	293055		
Address of School Corporation:	24795 Hinsley Rd						
City:	Sheridan	Zip:	46069	County Number:	29		
VIN:	4DRBWAAR4AA188958		License Number:	7617	Bus Number:	9	
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation	Year:	2010
Bus Type:	D			Mileage:	Unknown		
Inspection Status:	R	Inspected By:	John Pang	PE:	6196		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
99-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
99-1-7	Any emergency window is too difficult to open

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.