REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	7/30/2012	**Time:**	9:27 AM
Name of School Corporation:	SHERIDAN COMMUNITY SCHOOLS			**Corp ID:**	293055
Address of School Corporation:	24795 Hinsley Rd				
City:	Sheridan	**Zip:**	46069	**County Number:**	29
VIN:	4DRBWAAR4AA188958	**License Number:**	7617	**Bus Number:**	9
Make of Body:	IC Corporation **Year:** 2010	**Make of Chassis:**	IC Corporation	**Year:**	2010
Bus Type:	D	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
99-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
99-1-7	Any emergency window is too difficult to open

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.