

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	8/8/2012	<b>Time:</b>	1:56 PM
<b>Name of School Corporation:</b>	EMMANUEL-ST MICHAEL LUTHERAN SCHOOL (02)			<b>Corp ID:</b>	220011
<b>Address of School Corporation:</b>	1123 Union St				
<b>City:</b>	Ft Wayne	<b>Zip:</b>	46802	<b>County Number:</b>	2
<b>VIN:</b>	4UZABRDT6FCGB4706	<b>License Number:</b>	B272B	<b>Bus Number:</b>	5
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2015	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown	<b>Year:</b>	2015
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Tom Merkling	<b>PE:</b>	5390

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
58-1-1	Any required instrument or gauge is missing.
66-1-2	Any seat back or bottom is loose.
42-1-1	The flooring is improper.
83-1-2	Step-well area is weakened
37-1-1	The bus body has rust or rusted through areas which may weaken the body.
99-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
76-1-1	There are any loose, broken, or missing mountings
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**