## REPORT OF SCHOOL BUS INSPECTION

1:46

2009

Type of Annual Time: Date: 8/8/2012 Inspection: PM Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750 **Address of School Corporation:** 2 S 3rd St. County City: Flora Zip: 46929 8 Number: License VIN: 1BAKFCPH09F261573 30558 Bus Number: 2 Number:

Make of Blue Bird Blue Bird Year: 2009 Year: Make of Body: Corporation Chassis: Corporation

**Bus Type:** С Mileage: Unknown

Inspection Inspected 0 PE: Joel Flores 7415 Status: By:

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

108-2-1 Power lift does not operate in the proper manner

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.