REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/8/2012 Time: 11:23 AM

Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

City:FloraZip:46929County Number:8VIN:1FDWE35F13HB85204License Number:66833Bus Number:2sbMake of Body:Mid Bus, Inc. Year:2003Make of Chassis:FordYear:2003

Bus Type: Mileage: Unknown

Inspection Status: A Inspected By: Joel Flores PE: 7415

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description