REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	8/15/2012	Time:	10:06 AM
Name of School Co	orporation:	AVON	COMMUNITY	SCHOOLS		Corp ID:	323315
Address of School Corporation:			7203 E HWY 36				
City:	Avon	Z	Zip:	46123		County Number:	32
VIN:	4DRBWAAR19	9A07076	65	License Number:	31978	Bus Number:	21
Make of Body:	IC Corporation	Year: 2	2009	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	D			Mileage:	Unknown		
Inspection Status:	R	I	nspected By:	John Pang		PE:	6196

Violations - Rejected

Inspection CodeDescription30-1-8If required, positive door opening device is missing or fails to operate properly.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.