

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 8/17/2012	Time: 9:40 AM
Name of School Corporation:	CAROUSEL PLAY & LEARN CENTER	Corp ID: 420002
Address of School Corporation:	900 E. Montgomery Rd.	
City: Greensburg	Zip: 47240	County Number: 16
VIN: 1GBHG31RX11215706	License Number: B658BU	Bus Number: 1
Make of Body: Collins Bus Corporation	Year: 2001	Make of Chassis: Chevrolet
Year: 2001	Mileage: Unknown	Year: 2001
Bus Type: A1		
Inspection Status: O	Inspected By: Chris Clark	PE: 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
8-1-1	Required back-up lights do not function.
97-1-1	Washers do not function properly in any manner

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
15-2-5	There is brake fluid leaking at any point.

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.