

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	8/23/2012	Time:	10:03 AM		
Name of School Corporation:	AVON COMMUNITY SCHOOLS			Corp ID:	323315		
Address of School Corporation:	7203 E HWY 36						
City:	Avon	Zip:	46123	County Number:	32		
VIN:	4DRBWAAR78A642730	License Number:	31776	Bus Number:	133		
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	D	Mileage:	Unknown				
Inspection Status:	O	Inspected By:	John Pang	PE:	6196		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

14-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.