REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:8/22/2012Time:9:40 AMName of School Corporation:AVON COMMUNITY SCHOOLSCorp ID:323315

Address of School Corporation: 7203 E HWY 36

City:AvonZip:46123County Number:32VIN:4DRBRABNX2B947076License Number:18813Bus Number:89Make of Body:AmTranYear:2002Make of Chassis:IC CorporationYear:2002

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Chris Kath PE: 6690

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

38-1-1 Mirror or mirror backs that are loose or improperly mounted.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.