

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 8/23/2012	Time: 3:26 PM
Name of School Corporation: BLUE RIVER SERVICES	Corp ID: 450001	
Address of School Corporation: 3141 Progress Blvd.		
City: Corydon	Zip: 47112	County Number: 31
VIN: 1GBJG31U361188250	License Number: 21080	Bus Number: 99
Make of Body: Chevrolet	Year: 2006	Make of Chassis: Chevrolet
		Year: 2006
Bus Type: A2	Mileage: Unknown	
Inspection Status: R	Inspected By: Troy Boyd	PE: 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.