## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/23/2012 Time: 3:26 PM

Name of School Corporation: BLUE RIVER SERVICES Corp ID: 450001

Address of School Corporation: 3141 Progress Blvd.

City:CorydonZip:47112County Number: 31VIN:1GBJG31U361188250License Number: 21080Bus Number: 99Make of Body:Chevrolet Year: 2006Make of Chassis: Chevrolet Year: 2006

Bus Type: A2 Mileage: Unknown

Inspection Status: R Inspected By: Troy Boyd PE: 5171

## Violations - Rejected

Inspection Code Description

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.