

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|-----------------------|
| Type of Inspection: | Annual | Date: | 9/5/2012 | Time: | 11:39 AM |
| Name of School Corporation: | SMALL SMALL WORLD DAYCARE INDY | | | Corp ID: | 49DC2 |
| Address of School Corporation: | 440 St Peter St | | | | |
| City: | Indianapolis | Zip: | 46201 | County Number: | 49 |
| VIN: | 1GDL7T1E51J512316 | License Number: | C919470 | Bus Number: | 1 |
| Make of Body: | Blue Bird Corporation | Year: | 2001 | Make of Chassis: | Blue Bird Corporation |
| Bus Type: | C | Mileage: | Unknown | | |
| Inspection Status: | O | Inspected By: | Chris Kath | PE: | 6690 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 8-1-1 | Required back-up lights do not function. |
| 90-1-2 | One (1) taillight or one (1) brake light does not function |
| 34-1-4 | There is a significant fluid leak from the transmission. |
| 34-1-1 | There is significant engine oil or fluid leak from the engine. |
| 41-1-2 | The first aid kit is not properly filled in accordance with the '24 Unit Kit'. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 93-2-1 | Any rear turn signal does not function properly |
| 99-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.