

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	9/11/2012	<b>Time:</b>	11:41 AM
<b>Name of School Corporation:</b>	RICHLAND-BEAN BLOSSOM C.S.CORP			<b>Corp ID:</b>	535705
<b>Address of School Corporation:</b>	600 S Edgewood Dr				
<b>City:</b>	Ellettsville	<b>Zip:</b>	47429	<b>County Number:</b>	53
<b>VIN:</b>	1GDHG31R021218266	<b>License Number:</b>	19124	<b>Bus Number:</b>	49
<b>Make of Body:</b>	GMC	<b>Year:</b>	2002	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	A2	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Mark Raper	<b>PE:</b>	6473

**Violations - Rejected**

Inspection Code Description

**Violations - Out of Service**

<u>Inspection Code</u>	<u>Description</u>
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
18-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.

Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.