

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/27/2012	Time:	9:30 AM		
Name of School Corporation:	BLUE RIVER VALLEY SCHOOLS			Corp ID:	333405		
Address of School Corporation:	PO Box 217						
City:	Mount Summit	Zip:	47361	County Number:	33		
VIN:	4UZABRDK29CAA6662		License Number:	31151	Bus Number:	2	
Make of Body:	Thomas Built Buses, Inc.	Year:	2008	Make of Chassis:	Freightliner	Year:	2007
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Dave Whitinger	PE:	6480		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function
36-1-10	The location of the exhaust system has been altered from the original manufacture.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
23-2-1	Any crossmember is cracked or broken
99-2-1	Any glass or glazing is broken through or missing

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.