

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/1/2012 Time: 8:31 AM  
Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS Corp ID: 475075  
Address of School Corporation: 595 Stars Blvd  
City: Bedford Zip: 47421 County Number: 47  
VIN: 1FDXJ75C5RVA28976 License Number: 13571 Bus Number: A3  
Make of Body: Carpenter Year: 1994 Make of Chassis: Ford Year: 1994  
Bus Type: C Mileage: Unknown  
Inspection Status: R Inspected By: Mark Raper PE: 6473

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-5	Upholstery or padding is ripped, torn, or improperly repaired.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.