

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/1/2012	<b>Time:</b>	11:43 AM
<b>Name of School Corporation:</b>	RSI TRUCK & BUS REPAIR, INC	<b>Corp ID:</b>	45005Z		
<b>Address of School Corporation:</b>	3333 Sheffield Ave				
<b>City:</b>	Hammond	<b>Zip:</b>	46327	<b>County Number:</b>	45
<b>VIN:</b>	1GDL7T1DXXJ519939	<b>License Number:</b>	b535c	<b>Bus Number:</b>	15
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2000	<b>Make of Chassis:</b>	GMC
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	1999
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	David Eggers	<b>PE:</b>	5191

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
85-1-1	The stop arm lights do not flash alternately
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
85-2-3	Stop arm does not fully extend to a right angle to the bus
85-2-2	Stop arm lights do not flash
95-2-1	Warning lights fail to operate correctly

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**