REPORT OF SCHOOL BUS INSPECTION

Type of 10:52 Semi-Annual Time: Date: 10/1/2012 Inspection: AM Name of School Corporation: RSI TRUCK & BUS REPAIR, INC Corp ID: 45005Z **Address of School Corporation:** 3333 Sheffield Ave County City: Hammond Zip: 46327 45 Number: License VIN: B300G 1HVBBAAP6XH236288 **Bus Number:** Number: Make of IC Blue Bird **Year:** 1999 1999 Make of Body: Year: Corporation Corporation Chassis: **Bus Type:** С Mileage: Unknown Inspection Inspected 0 PE: David Eggers 5191 Status: By:

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection

<u>Code</u>	<u>Description</u>
34-2-2	There is a significant leak from the engine or transmission onto the exhaust system
	which could potentially cause a fire.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.