

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	9/28/2012	Time:	8:34 AM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600
Address of School Corporation:	6109 Squire Place				
City:	Aurora	Zip:	47001	County Number:	15
VIN:	1HVBGAANSTA074408	License Number:	B583D	Bus Number:	28A
Make of Body:	IC Corporation	Year:	1996	Make of Chassis:	IC Corporation
Year:				Year:	1996
Bus Type:	D	Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-5	Upholstery or padding is ripped, torn, or improperly repaired.
20-1-5	The timer does not automatically set
20-1-6	The horn fails to work intermittently and continuously after the time delay has expired
20-1-3	The indicator light is not labeled
20-1-2	There is no indicator light in view of driver.
20-1-4	The amount of time delay exceeds one minute.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.