

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 10/2/2012 **Time:** 10:00 AM
Name of School Corporation: PRIMROSE SCHOOL OF W. FISHERS **Corp ID:** 290004
Address of School Corporation: 12609 Parkside Dr.
City: Fishers **Zip:** 46038 **County Number:** 29
VIN: 1GBHG31C681181818 **License Number:** B930AC **Bus Number:** 2
Make of Body: Chevrolet **Year:** 2008 **Make of Chassis:** Chevrolet **Year:** 2008
Bus Type: A1 **Mileage:** Unknown
Inspection Status: O **Inspected By:** Amy Gaul **PE:** 5934

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
81-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.