

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 10/3/2012 Time: 10:16 AM
Name of School Corporation: MARQUETTE HIGH SCHOOL Corp ID: 71002Z
Address of School Corporation: 306 W 10th St.
City: Michigan City Zip: 46306 County Number: 46
VIN: 1GBHG31R6Y1201361 License Number: b872aa Bus Number: 1
Make of Body: Chevrolet Year: 2000 Make of Chassis: Corbeil Year: 2000
Bus Type: Mileage: Unknown
Inspection Status: O Inspected By: David Eggers PE: 5191

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 41-1-2 | The first aid kit is not properly filled in accordance with the '24 Unit Kit'. |
| 61-1-2 | Any required lettering is missing or faded. |

Violations - Out of Service

Inspection Code Description

Bus Type Description