

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	10/19/2012	<b>Time:</b>	2:01 PM
<b>Name of School Corporation:</b>	CLINTON PRAIRIE SCHOOL CORP.	<b>Corp ID:</b>	121160		
<b>Address of School Corporation:</b>	4431 W SR 28				
<b>City:</b>	Frankfort	<b>Zip:</b>	46041	<b>County Number:</b>	12
<b>VIN:</b>	1HVBBAAN72H547946	<b>License Number:</b>	18651	<b>Bus Number:</b>	5
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2003	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Joel Flores	<b>PE:</b>	7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
97-1-1	Washers do not function properly in any manner
98-1-2	Wiper blades fail to contact the windshield properly
21-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
38-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.
38-2-2	Reflective glass is cracked, broken, or missing.
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
98-2-1	Wipers fail to function
85-2-4	Stop arm does not function properly

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**