

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/19/2012	Time:	2:01 PM		
Name of School Corporation:	CLINTON PRAIRIE SCHOOL CORP.			Corp ID:	121160		
Address of School Corporation:	4431 W SR 28						
City:	Frankfort	Zip:	46041	County Number:	12		
VIN:	1HVBBAAN72H547946		License Number:	18651	Bus Number:	5	
Make of Body:	Blue Bird Corporation	Year:	2003	Make of Chassis:	IC Corporation	Year:	2003
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
97-1-1	Washers do not function properly in any manner
98-1-2	Wiper blades fail to contact the windshield properly
21-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
38-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.
38-2-2	Reflective glass is cracked, broken, or missing.
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
98-2-1	Wipers fail to function
85-2-4	Stop arm does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.