REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	10/22/2012	**Time:**	9:28 AM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31RXX1146766	**License Number:**	B958AB	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1999	**Make of Chassis:**	Chevrolet	**Year:**	1999
Bus Type:		**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Amy Gaul	**PE:**	5934

Violations - Rejected

Inspection Code	Description
90-1-2	One (1) taillight or one (1) brake light does not function
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

Violations - Out of Service

Inspection Code	Description

Bus Type Description