

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/22/2012 **Time:** 9:28 AM
Name of School Corporation: HONEY GROVE EDUCATIONAL DAYCARE **Corp ID:** 41001Z
Address of School Corporation: 1709 S SR 135
City: Greenwood **Zip:** 46143 **County Number:** 41
VIN: 1GBHG31RXX1146766 **License Number:** B958AB **Bus Number:** 2
Make of Body: Chevrolet **Year:** 1999 **Make of Chassis:** Chevrolet **Year:** 1999
Bus Type: **Mileage:** Unknown
Inspection Status: R **Inspected By:** Amy Gaul **PE:** 5934

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

Violations - Out of Service

Inspection Code Description

Bus Type Description