

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/23/2012	Time:	3:23 PM
Name of School Corporation:	NORTH GIBSON SCHOOL CORP.			Corp ID:	262735
Address of School Corporation:	1108 N Embree St				
City:	Princeton	Zip:	47670	County Number:	26
VIN:	4DRBWAAR95A983509			License Number:	20791
Make of Body:	IC Corporation	Year:	2005	Make of Chassis:	IC Corporation
Bus Type:	D	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Chuck Tharp	PE:	5618

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
93-1-4	Any front turn signal does not function properly
93-1-2	A lens is cracked, missing or wrong color
62-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative.
10-1-4	Battery terminals are excessively corroded.
30-1-8	If required, positive door opening device is missing or fails to operate properly.
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
18-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
38-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.